



Be fire smart in your shop

THE BIGGEST THREAT OF FIRE IN YOUR SHOP MIGHT BE A \$50,000 VEHICLE—OR A 5-CENT RAG.

Two dealerships recently experienced catastrophic fires that were ignited in vehicles left in the service shop overnight. Resulting expenses included:

\$4.7M

average insured damages per case

12

months of prolonged recovery


\$300K

uninsured expenses absorbed by each business

Be proactive to prevent fires in your shop. We're here to help. Visit us at [sentry.com](https://www.sentry.com).

Safety services are provided by a member of the Sentry Insurance Group, Stevens Point, WI. For a complete listing of companies, visit [sentry.com](https://www.sentry.com).

This document is made available by Sentry Insurance a Mutual Company and its subsidiaries and affiliates (collectively "SIAMCO") with the understanding that SIAMCO is not engaged in the practice of law, nor is it rendering legal advice. The information contained in this document is of a general nature and is not intended to address the circumstances of any particular individual or entity. Legal obligations may vary by state and locality. No one should act on the information contained in this document without legal advice from competent and licensed local professionals. THE INFORMATION CONTAINED IN THIS DOCUMENT IS DISTRIBUTED BY SIAMCO "AS-IS", WITHOUT ANY WARRANTIES. SIAMCO WILL HAVE NO LIABILITY TO ANY PERSON OR ENTITY WITH RESPECT TO ANY LOSSES OR DAMAGES CAUSED, OR ALLEGED TO HAVE BEEN CAUSED, DIRECTLY OR INDIRECTLY BY THIS DOCUMENT, REGARDLESS OF WHETHER SUCH CLAIM IS BASED ON CONTRACT, WARRANTY, TORT (INCLUDING NEGLIGENCE AND FOR PROPERTY DAMAGE AND DEATH) OR OTHER GROUNDS.



Help prevent fire from roll-in risks

During the day

Before you leave

Document

all indications of electrical, fuel, or hydraulic system symptoms on service orders.



Dispose

oily/solvent rags in an approved container to prevent spontaneous combustion.




Disconnect

batteries and chargers so they don't spark a fire overnight.



Shut off

any fuel switches after hours.



Isolate

at-risk vehicles outside until they can be serviced.

